



**Outsulation® MD System®**



Dryvit Technical Support: 800-556-7752

Detail: Horizontal Termination at Lap Siding

Drawn by: KAB

Checked by: CB

Scale: NTS

1/2022

File Name:

OMD 31



Construction Products Group

www.tremcoapg.com